

Date: Feb. 16, 2018

Subject: Small leak of oily water

On Thursday, February 15th, an outdoor open-topped metal recycling bin was discovered to be leaking through an open drain hole. Less than 10 litres of oily water had leaked onto the concrete pad and adjacent grass. The spill was contained and cleaned up and repairs are being made to the recycling bin. There was no off-site leak and no health or safety risk posed to employees or members of the public.